



SETUP INSTRUCTIONS

Step 1: Slide Aluminum Foot (A) into Bottom Profile (B) until it reaches the midpoint.

Step 2: Hook top of Three Part Pole (D) into Top Profile (C). Insert Three Part Pole (D) into Aluminum Foot (A) at the bottom.

Step 3: Insert Light (E) into top of the Three Part Pole (D).

Note: When collapsing the stand it is important to hold the graphic with your hand to avoid damage to the graphic.

PARTS

- (A) Aluminum Foot
- (B) Bottom Profile
- (C) Top Profile
- (D) Three Part Pole
- (E) Light

